



Panasonic Service STWin

29. REPLACEMENT PARTS


CS-71E95JP, CS-80E95JP, CS-112E95JP, CS-140E95JP, CS-160E95JP




CU-71C52HP, CU-71C52XP, CU-80C52HP, CU-80C52XP




CU-71C52HP, CU-71C52XP, CU-80C52HP, CU-80C52XP




CU-71C52HP, CU-71C52XP, CU-80C52HP, CU-80C52XP (Heat pump model)




CU-71C02HP, CU-71C02XP, CU-80C02HP, CU-80C02XP (Cooling only model)




CU-112C52XP, CU-140C53XP, CU-160C53XP



CU-112C52XP, CU-140C53XP, CU-160C53XP



CU-112C52XP, CU-140C53XP, CU-160C53XP (Heat pump model)



CU-112C02XP, CU-140C03XP, CU-160C03XP (Cooling only model)

