Service Information

2000-04-01
TC(X)
DAP240

Domestic Appliances and Personal Care

Service Information DAP130 = 4822 729 21704 is herewith cancelled.

This Service Information belongs to Service Manual: TC4.., TC5.. = 4822 729 21222

TC6.., TC7.., TC8.. = 4822 729 21223 TCX4.., TCX5.. = 4822 729 21469 TCX6.., TCX7.., TCX8.. = 4822 729 21471


Vacuum cleaners without electronic remote control.

All spare dust covers will be standardised to one colour: black.

In most cases, defective swivels, which are part of the dust cover, can be replaced by breaking them out of the dust cover by means of, for example, a vacuum cleaner tube.

NEW SPARE PART.

Swivel of dustchamber cover has code number: 4322 009 07650.



1. 4822 417 11334 Hose lock

2. 4322 009 07650 Swivel

3. 4822 532 70286 Sealing ring

4. 4822 402 90001 Snap lock



4322 277 00298 PCS 101 483